


Report on Extent of Damage due to Cloudburst Induced Flooding in the Teesta Basin as on 16.00 Hrs. 13th OCTOBER 2023

Name of the Districts affected	No. of Villages/ Wards/ Nagar Panchayat/ Councils affected	No. of Population affected	No. of Human Lives Lost	No. of people missing	No. of Persons who suffered grievous injury requiring hospitalization	No. of Damaged Houses	Fully and Severely damaged Pucca and Kutcha House	Partially Damaged Pucca House	Partially Damaged Kutcha House	No. of people Rescued	No. of Evacuated	No. of Relief Camps Opened	No. of Inmates in Relief Camps	Animal and Poultry Lost	No. of persons living in the Rented Houses affected	No. of Shops affected	No. of Bridges washed away
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15			16
Mangan	50	30300	04	17	04 (02 - Indian Army)	547	247	91	209	850	2640 People evacuated by Chopper/Foot Tourists 1872 Locals 336	03	303	Animal - 997 Poultry - 6653 Others - 507	190	38	26
Gangtok	19	20000	07	25	05	319	241	30	48	1025	1025	08	1531	Animal - 106 Poultry - 7943	2500	300	03
Pakyong	07	30000	14+ 10 (Indian Army)	30	21	635	635	-	-	58	58	05	919	Animal - 303 Poultry - 8987	1119	220	-
Namchi	24	8100	02	06	-	482	300	45	137	630	630	03	271	Animal - 316 Poultry - 2125	175	33	04
Total	100	88400	37	78	30	1983	1423	166	394	2563	4353	19	3024		3984	591	33

Copy for kind info. to:

- i. The Chief Secretary, Govt. of Sikkim.
- ii. The Secretary to the Hon'ble Governor.
- iii. Secretary to HCM, Office of the HCM.
- iv. The PS to HM, LR&DM Deptt.
- v. The Secretary/PR.
- vi. The DC, Gangtok/Mangan/Pakyong/Namchi.




 Secretary-cum-State Relief Commissioner
 Land Revenue & Disaster Management Department
 Government of Sikkim, Gangtok

DETAIL LIST OF RELIEF CAMPS AND INMATES PRESENTLY STAYING IN THE RELIEF CAMPS

Districts	No. of Relief Camp Operational	Loss and Damage to Infrastructure
Mangan	03 Nos. i. ITI, Chaday - 64 ii. Naga – 157 iii. Chungthang Gurudwara- 82	<p>i. Chungthang Sikkim Urja Dam washed away.</p> <p>ii. Toong Naga GPU affected.</p> <p>iii. Road damaged between Toong and Naga.</p> <p>vi. Police Office Quarter, Pass-Permit Entry Check Post & Fire Office Damaged at Phidang.</p> <p>v. Office of the Range Officer Territory Damaged at Dzongu.</p> <p>vi. Moon Light Private School Building/ Forest store.</p> <p>vii. Chungthang 4 no. RCC Foot- bridge washed away.</p> <p>viii. Lachung Dzomsa 2 no. RCC Foot Bridge washed away.</p> <p>ix. Passingdong 1 no. RCC Foot Bridge washed away.</p> <p>x. Namprickdang Playground Gallery & 3 units RCC toilet damage.</p> <p>xi. 80% of Chungthang Town severely affected.</p> <p>xii. GREF crusher plant and Toong Police Check-post.</p> <p>xiii. Forest Guest House, Namprickdang.</p> <p>xiv. Lepcha Traditional House washed away.</p> <p>xv. Naga/Power Office and Quarter damaged.</p> <p>xvi. Lachen Dzumsa 5 no. RCC Foot bridge washed away.</p> <p>xvii. Shipgyer 2 no. RCC Foot Bridge washed away.</p> <p>xviii. Toong Naga 3 no. RCC Foot Bridge washed away.</p> <p>xix. Firing Bridge at Chungthang.</p>
Gangtok	08 Nos. i. Singtam Govt. Sr. Sec School - 541 ii. Bihari Bhawan- 572 iii. Food Preservation Factory – 15 iv. Pranami Mandir Singtam – 74 v. Masjid Singtam – 111 vi. Singtam Church – 92 vii. Medhavi Skill University - 57 viii. Marwari Dharamshala - 69	<p>i. Indreni Bridge in Singtam washed out.</p> <p>ii. NH -10 highway has sustained extensive damage.</p> <p>iii. Sewage Treatment plant and pipelines washed in Singtam.</p> <p>iv. Sneha Kinetic Powerhouse and NHPC dam site have been submerged.</p> <p>v. Balutar bridge washed away and extensive damages of State Highway along Balutar/Sirwani/ Goshkhan Area.</p>
Pakyong	05 Nos. i. Chanatar Govt Secondary School -302 ii. Majhitar Govt. Secondary School & Mining Govt Sr. Sec School - 87 iii. Majhigaon Housing Complex - 223 iv. Golitar Nepali Dharamshala - 255 v. Eco Paradise - 52	<p>i. Sewerage Treatment Plant and pipelines washed away in Rangpo.</p> <p>ii. NH-10 has sustained extensive damages.</p> <p>iii. IBM totally submerged in floods, Rangpo, Baghey Khola, Majhitar, Bardang are severely affected by .</p> <p>iv. Baghey Khola River side habitations have been submerged.</p> <p>v. Course of Teesta River changed and caused extensive damage to the properties at various locations.</p> <p>vi. Power Supply lines have been damaged extensively.</p> <p>vii. PHE/ Storage along with pipelines are extensively damaged at IBM and Golitar.</p> <p>viii. Under construction bridge at Golitar, Singtam has been damaged.</p>
Namchi	03 Nos i. Pranami Mandir, Namphing - 214 ii. Recep Primary School – 24 iii. NHPC Primary School Linkutar - 33	<p>i. LD Kazi Bridge washed away.</p> <p>ii. Sewerage Treatment Plant and pipelines washed away in Melli.</p> <p>iii. Steel Foot bridge over Teesta River connecting 20th Mile to Chalamthang in Namchi District.</p> <p>iv. Steel Bridge connecting Kabrey, Namchi District to Majitar in Gangtok District.</p> <p>v. Steel Foot bridge of Lanco Pvt. Ltd over Teesta River connecting Pamphok (Thalthaley to Tar Khola, WB)</p>
Total	Relief Camps - 19 Nos. Inmates in Relief Camps – 3024	



Secretary-cum- State Relief Commissioner
Land Revenue & Disaster Management Department
Government of Sikkim, Gangtok