Report on Extent of Damage due to Cloudburst Induced Flooding in the Teesta Basin as on 15.00 Hrs. 15th OCTOBER 2023

Total	Namchi	Pakyong	Gangtok	Mangan	ם	Name of the Districts affected
100	24	07	19	50	2	No. of Villages / Wards/ Nagar Panchayat/ Councils affected
88400	8100	30000	20000	30300	ω	No. of Population affected
38	02	14 + 10 (Indian Army)	08	04	4	No. of Human Lives Lost
76	05	28	23	20	5	No of people missing
30		21	05	04 (02 – Indian Army)	6	No. of Persons who suffered grievous injury requiring hospitalization
2002	482	635	319	566	7	No. of Damaged Houses
1423	300	635	241	247		Fully and Severely damaged Pucca and Kutcha House
166	45	,	30	91	9	Partially Damaged Pucca House
413	137		48	228	10	Partially Damaged Kutcha House
2563	630	58	1025	850	11	No of people Rescued
4357	630	58	1025	2644 People evacuated by Chopper/Foot Tourists Locals 1876 336	12	No of People Evacuated
20	02	06	08	04	13	No. of Relief Camps Opened
2321	195	779	1091	256	14	No. of Inmates in Relief Camps
	Animal - 316 Poultry - 2125	Animal- 303 Poultry - 8987	Animal - 215 Poultry- 11624	Animal - 997 Poultry- 6653 Others- 507	15	Animal and Poultry Lost
5019	850	1119	2500	550		No of persons living in the Rented Houses affected
922	44	220	600	58		No of Shops affected
33	04	•	03	26	16	No of Bridges washed away



vi. The DC, Gangtok/Mangan/Pakyong/Namchi.

v. The Secretary/IPR.

iii. Secretary to HCM, Office of the HCM.
iv. The PS to HM, LR&DM Deptt.

Copy for kind info. to:
i. The Chief Secretary, Govt. of Sikkim.
ii. The Secretary to the Hon'ble Governor.



Total	Namchi	Pakyong	Gangtok	Mangan	Districts
Relief Camps - 20 Nos. Inmates in Relief Camps – 2321	02 Nos i. Pranami Mandir, Namphing - 180 ii. NHPC Primary School Linkutar - 15	 06 Nos. i. Chanatar Govt Secondary School -70 ii. Majhigaon Housing Complex - 285 iii. Golitar Nepali Dharamshala - 238 iv. Eco Paradise – 62 v. SDL, Hall Chanatar – 99 vi. EPCH Church – 25 	i. Singtam Govt. Sr. Sec School - 360 ii. Bihari Bhawan - 401 iii. Food Preservation Factory – 15 iv. Pranami Mandir Singtam – 25 v. Masjid Singtam – 90 vi. Singtam Church – 75 vii. Medhavi Skill University - 56 viii. Marwari Dharamshala - 69	i. ITI, Chaday - 38 ii. Naga – 155 iii. Chungthang Gurudwara- 42 iv. Chungthang Shiv Mandir - 23	No. of Relief Camp Operational
v. Steel Bridge connecting Kabrey, Namchi District to Majitar in Gangtow District. v. Steel Foot bridge of Lanco Pvt. Ltd over Teesta River connecting Apriphok (Nta)thaley to Tar Khola, WB) (3) (4) (5) (5) (5) (5) (5) (6) (7) (7) (7) (8) (8) (9) (9) (9) (9) (9) (9	i. LD Kazi Bridge washed away. ii. Sewerage Treatment Plant and pipelines washed away in Melli. Ill. Steel Foot bridge over Teesta River connecting 20th Mile to Chalamthang in Namchi District.	 i. Sewerage Treatment Plant and pipelines washed away in Rangpo. ii. NH-10 has sustained extensive damages. iii. IBM totally submerged in floods, Rangpo, Baghey Khola, Majhitar, Bardang are severely affected. iv. Baghey Khola River side habitations have been submerged. v. Course of Teesta River changed and caused extensive damage to the properties at various locations. vi. Power Supply lines have been damaged extensively. vii. PHE/ Storage along with pipelines are extensively damaged at IBM and Golitar. viii. Under construction bridge at Golitar, Singtam has been damaged 	 i. Indreni Bridge in Singtam washed out. ii. NH -10 highway has sustained extensive damage. iii. Sewage Treatment plant and pipelines washed in Singtam. iv. Sneha Kinetic Powerhouse and NHPC dam site have been submerged. v. Balutar bridge washed away and extensive damages of State Highway along Balutar/Sinwani/ Goshkhan Area. 	i. Chungthang Sikkim Urja Dam washed away. ii. Toong Naga GPU affected. iii. Toong Naga GPU affected. iii. Road damaged between Toong and Naga. vi. Police Office Quarter, Pass-Permit Entry Check Post & Fire Office Damaged at Phidang. v. Office of the Range Officer Territory Damaged at Dzongu. xv. Naga/Power Office and Quarter damaged vi. Moon Light Private School Building/ Forest store. vii. Chungthang 4 no. RCC Foot-bridge washed away. viii. Lachung Dzomsa 2 no. RCC Foot-bridge washed away. ix. Passingdong 1 no. RCC Foot Bridge washed away. ix. Passingdong 1 no. RCC Foot Bridge washed away. xi. Namprickdang Playground Gallery & 3 units RCC toilet damage. xx. Hatchery unit at Chungthang totally washed away xxi. Firing Bridge at Chungthang totally washed away xxi. 80% of Chungthang Town severely affected. xxii. GREF crusher plant and Toong Police Check-post. xiii. Forest Guest House, Namprikdang xiv. Lepcha Traditional House washed away. xiv. Lepcha Traditional House washed away. xvi. Lachen Dzumsa 5 no. RCC Foot Bridge washed away. xvii. Shipgyer 2 no. RCC Foot Bridge washed away. xviii. Toong Naga 3 no. RCC Foot Bridge washed away. xiii. Firing Bridge at Chungthang totally washed away xxi. 80% of Chungthang Town severely affected. xxiii Forest Guest House, Namprikdang xii Forest Guest House, Namprikdang	Loss and Damage to Infrastructure