

## Report on Extent of Damage due to Cloudburst Induced Flooding in the Teesta Basin as on 16.00 Hrs. 18<sup>th</sup> OCTOBER 2023

Name of the Districts affected	No. of Villages / Wards/ Nagar Panchayat/ Councils affected	No. of Population affected	No. of Human Lives Lost	No of people missing	No. of Persons who suffered grievous injury requiring hospitalization	No. of Damaged Houses	Fully and Severely damaged Pucca and Kutcha House	Partially Damaged Pucca House	Partially Damaged Kutcha House	No of people Rescued	No of People Evacuated	No. of Relief Camps Opened	No. of Inmates in Relief Camps	Animal and Poultry Lost	No of persons living in the Rented Houses affected	No of Shops affected	No of Bridges washed away	
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15			16	
Mangan	50	30300	04	23	-	566	247	91	228	850	<b>2883</b>	03	218	Animal - 997 Poultry- 6653 Others- 507	550	58	26	
											People evacuated by Chopper/Foot							
											Tourists							Locals
											1876	1007						
Gangtok	19	20000	08	23	05	319	241	30	48	1025	1025	06	551	Animal - 215 Poultry- 11624	2500	600	03	
Pakyong	07	30000	15 + 11 (Indian Army)	28	21	635	635	-	-	58	58	05	437	Animal- 303 Poultry - 8987	1119	220	-	
Namchi	24	8100	02	05	-	482	300	45	137	630	630	02	141	Animal - 316 Poultry - 2125	850	44	04	
<b>Total</b>	<b>100</b>	<b>88400</b>	<b>40</b>	<b>79</b>	<b>26</b>	<b>2002</b>	<b>1423</b>	<b>166</b>	<b>413</b>	<b>2563</b>	<b>4596</b>	<b>16</b>	<b>1347</b>		<b>5019</b>	<b>922</b>	<b>33</b>	

Copy for kind info. to:

- i. The Chief Secretary, Govt. of Sikkim.
- ii. The Secretary to the Hon'ble Governor.
- iii. Secretary to HCM, Office of the HCM.
- iv. The PS to HM, LR&DM Deptt.
- v. The Secretary/IPR.
- vi. The DC, Gangtok/Mangan/Pakyong/Namchi.




  
 Secretary-cum-Secretary Relief Commissioner  
 Land Revenue & Disaster Management Department  
 Government of Sikkim, Gangtok

**DETAIL LIST OF RELIEF CAMPS AND INMATES PRESENTLY STAYING IN THE RELIEF CAMPS**

Districts	No. of Relief Camp Operational	Loss and Damage to Infrastructure	
Mangan	<b>03 Nos.</b> i. Naga – 153 ii. Chungthang Gurudwara- 42 iii. Chungthang Shiv Mandir - 23	i. Chungthang Sikkim Urja Dam washed away. ii. Toong Naga GPU affected. iii. Road damaged between Toong and Naga. vi. Police Office Quarter, Pass-Permit Entry Check Post & Fire Office Damaged at Phidang. v. Office of the Range Officer Territory Damaged at Dzongu. vi. Moon Light Private School Building/ Forest store. vii. Chungthang 4 no. RCC Foot- bridge washed away. viii. Lachung Dzomsa 2 no. RCC Foot Bridge washed away. ix. Passingdong 1 no. RCC Foot Bridge washed away. x. Namprickdang Playground Gallery & 3 units RCC toilet damage. xi. 80% of Chungthang Town severely affected.	xii. GREF crusher plant and Toong Police Check-post. xiii. Forest Guest House, Namprickdang xiv. Lepcha Traditional House washed away. xv. Naga/Power Office and Quarter damaged xvi. Lachen Dzumsa 5 no. RCC Foot bridge washed away. xvii. Shipgyer 2 no. RCC Foot Bridge washed away. xviii. Toong Naga 3 no. RCC Foot Bridge washed away. xix. Firing Bridge at Chungthang. xx. Hatchery unit at Chungthang totally washed away xxi. Fisheries Dept. Office Building washed away
Gangtok	<b>06 Nos.</b> i. Singtam Govt. Sr. Sec School - 83 ii. Bihari Bhawan- 339 iii. Food Preservation Factory – 15 iv. Pranami Mandir Singtam – 25 v. Medhavi Skill University - 31 vi. Marwari Dharamshala – 58	i. Indreni Bridge in Singtam washed out. ii. NH -10 highway has sustained extensive damage. iii. Sewage Treatment plant and pipelines washed in Singtam. iv. Sneha Kinetic Powerhouse and NHPC dam site have been submerged. v. Balutar bridge washed away and extensive damages of State Highway along Balutar/Sirwani/ Goshkhan Area.	
Pakyong	<b>05 Nos.</b> i. Majhigaon Housing Complex - 140 ii. Golitar Nepali Dharamshala - 204 iii. Eco Paradise – 40 iv. SDL, Hall Chanatar – 09 vi. EPCH Church – 44	i. Sewerage Treatment Plant and pipelines washed away in Rangpo. ii. NH-10 has sustained extensive damages. iii. IBM totally submerged in floods, Rangpo, Baghey Khola, Majhitar, Bardang are severely affected. iv. Baghey Khola River side habitations have been submerged. v. Course of Teesta River changed and caused extensive damage to the properties at various locations. vi. Power Supply lines have been damaged extensively. vii. PHE/ Storage along with pipelines are extensively damaged at IBM and Golitar. viii. Under construction bridge at Golitar, Singtam has been damaged.	
Namchi	<b>02 Nos</b> i. Pranami Mandir, Namphing - 127 ii. NHPC Primary School Linkutar - 14	i. LD Kazi Bridge washed away. ii. Sewerage Treatment Plant and pipelines washed away in Melli. III. Steel Foot bridge over Teesta River connecting 20 <sup>th</sup> Mile to Chalamthang in Namchi District. iv. Steel Bridge connecting Kabrey, Namchi District to Majitar in Gangtok District. v. Steel Foot bridge of Lanco Pvt. Ltd over Teesta River connecting Pamphok (Thalthaley to Tar Khola, WB)	
Total	Relief Camps - 16 Nos. Inmates in Relief Camps – 1347		



  
 Secretary-cum-State Relief Commissioner  
 Land Revenue & Disaster Management Department  
 Government of Sikkim, Gangtok